

st Report	No.:	SZXEC25000588601	Date:	Mar 10, 2	2025	Page 1 of
Client Name:	SHENZHEN S	KY SEMICONDUCTOR CO.	,LTD			
	4TH FLOOR (DISTRICTSHI	DINGBANG TOWER ANO.4 I ENZHEI	NORTHHI-T	ECH AVE,	NANSHAN	
Sample Name:	Т	OLL				
Model No.:	Т	OLL				
Client Ref. Inform	- 	TO-220,TO-220-2L,TO-220F, TO-252-4L,PTO252,TO-3P,T TO-247-4L,TO-263,TO-263-6 DFN3*3,DFN3.3*3.3,DFN5*6 PDFN3.3*3.3,PDFN5*6,PDFN SOP-16,TSOP-6,TSOP-8,TS S-TOLL DSC, S-DPAK,TOLT _FPAK56,LFPAK56 DSC mation were provided by the	O-3P-2L,TC L,TO-263-7 ,DFN8*8,PE N8*8,SOP-6 OP-12,TSO , PDFN5*6 client.)-247,TO-2 L,TO-262,I)FN3*2,PD ,SOP-8,SC P-16.S-TO DSC,TOL	247-2L, DFN3*2, FN3*3, DP-12, LL, L DSC,	
SGS Job No.:		ZP25-008523				
Sample Receivir	ng Date: N	lar 04, 2025				
Testing Period:	Ν	/lar 04, 2025 ~ Mar 10, 2025				
Test Requested:	S	Select test(s) as requested by	the client.			
Test Method(s):	F	Please refer to next page(s).				
Test Result(s):	F	Please refer to next page(s).				
Test Requirem	nent				Conclu	sion
Halogen					See Re	sults

Signed for and on behalf of SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch

lina

Tina Fan Approved Signatory



4



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>https://www.sgs.com/en/Terms-and-Conditions</u>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction form exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone; (86-755) 8307 1443, or email: CN_Doccheck@sgs.com

Room 101-901, Plant 4& Room 101, Plant 2& Room 301-501, Plant 3, Janghao (Bantian) Industrial Plant Area, No. 430, Jhua Road, Bantian Community, Bantian Street, Loggang District, Shenchen, Guangdong, China 518(2) www.sagesgroup.com.cn 中国・广东・深圳市志岗区坂田街道坂田社区吉华路430号江斎(坂田)工业厂区厂房4号101-901、2号101、3号101、3号301-501 廠場:518129 t(86-755) 25328888 sgs.china@sgs.com



Test Report

No.: SZXEC25000588601

Date: Mar 10, 2025

Test Result(s):

Test Part Description:

SN ID	Sample No.	SGS Sample ID	Description
SN1	A1	SZX25-0005886-0001.C001	Black plastic A1

Remarks:

- (1) 1 mg/kg = 1 ppm = 0.0001%
- (2) MDL = Method Detection Limit
- (3) ND = Not Detected (< MDL)
- (4) "-" = Not Regulated

<u>Halogen</u>

Test Method: With reference to EN 14582:2016, analysis was performed by IC.

Test Item(s)	Unit(s)	MDL	A1
Fluorine(F)	mg/kg	20	ND
Chlorine(Cl)	mg/kg	50	ND
Bromine(Br)	mg/kg	50	ND
lodine(l)	mg/kg	50	ND

Unless otherwise stated, the decision rule for conformity reporting is based on Binary Statement for Simple Acceptance Rule (*w*=0) stated in ILAC-G8:09/2019.



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or faisification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com


 Room 101-907, Paint 4& Room 101, Plant 2& Room 101, Plant 3& Room 301-507, Plant 3, Kangbao (Bantian) Industrial Plant Area, No. 400, Ilina Road, Bantian Community, Bantian Steet, Longgang District, Stenzien, Gaugdong, China 516129 www.segsgroup.com.cn 中国・广东・深圳市龙岗区坂田街道坂田社区吉华路430号江源(坂田)工业厂区厂房4号101-901、2号101、3号301-501 邮编-518129 t(86-755) 25328888 sgs.china@sgs.com



Test Report ATTACHMENTS

No.: SZXEC25000588601

Halogen Testing Flow Chart






Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or faisification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

d. Room 101-400, Plant 4& Room 101, Plant 2& Room 101, Plant 3& Room 301-500, Plant 3, Jacoptao (Bastian) Industrial Plant Area, No. 430, Jiana Road, Santian Community, Bastian Steet, Longgang District, Steenzien, Gaugolong, China 51029 www.segsgroup.com.cn 中国・广东・深圳市龙岗区坂田街道坂田社区吉华路430号江源(坂田)工业厂区厂房4号101-901、2号101、3号301-501 邮编:518129 t(86-755) 25328888 sgs.china@sgs.com





SGS authenticate the photo on original report only *** End of Report ***



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN_Doccheck@sgs.com

 Room 101-907, Paint 4& Room 101, Plant 2& Room 101, Plant 3& Room 301-507, Plant 3, Kangbao (Bantian) Industrial Plant Area, No. 400, Ilina Road, Bantian Community, Bantian Steet, Longgang District, Stenzien, Gaugdong, China 516129 www.segsgroup.com.cn 中国・广东・深圳市龙岗区坂田街道坂田社区吉华路430号江源(坂田)工业厂区厂房4号101-901、2号101、3号301-501 邮编-518129 t(86-755) 25328888 sgs.china@sgs.com